ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0579, W0418, W0370, W0577, W0583, W0591, W0595	5th Crs, 7th Crs Gramatana, NA, 3rd Crs	Sri M V LAYOUT 5TH Cross
Segment No.	**Total Length (m)**	
9/C-W0579/S095012	271.57	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	39.33	77.572539	13.071636	77.572628	13.071980	W0370	W0364
2	30.22	77.572261	13.071717	77.572322	13.071983	W0370	W0364
3	24.68	77.572014	13.071792	77.572067	13.072009	W0370	W0364
4	22.40	77.571641	13.071871	77.571711	13.072061	W0370	W0364
5	154.94	77.570455	13.069920	77.571785	13.069408	W0579	W0601

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Sri M V LAYOUT 5TH Cross and other Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	100000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements and Asphalting to Sri M V LAYOUT 5TH Cross and other Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	009-16-000016
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/343/2015-16	30/03/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/03/2016	29/03/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
R.MADHUSUDHAN		0.00
Phone No.	**E-Mail ID**	
9019996726		

Field Inspection Details

Number of Trees	Any Other Information	Name
12		MADHAVA RAO
Date of Inspection	**Remarks**	
10/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0579, W0418, W0370, W0577,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	10/12/2016	09/01/2017	COMPLETED
SE	VASU K M	10/12/2016	09/01/2017	COMPLETED
EE	YARAPPA REDDY	10/12/2016	09/01/2017	COMPLETED
AEE	SHIVAKUMAR	10/12/2016	09/01/2017	COMPLETED
AE	MADHAV RAO	10/12/2016	09/01/2017	COMPLETED
AE	MADHAV RAO	10/12/2016	09/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0579, W0418, W0370, W0577,